

Photo inspection report

Sample office entrance

DEMO-2026-0927

Client: Fictional office

Auditor: Demo inspector

Report selection: All


Assigned to: All

Due on or before: All

Findings: 1 / 1

Unresolved 0 · In progress 0 · Resolved 1

EXAMPLE PLAN / NOT TO SCALE



Fictional office entrance. Door finding is marked by the app.

Finding 1 · Door alignment at entrance

Ground floor / entrance door · Resolved

Assigned to: Sample maintenance team

Due date: 2026-09-27

Fictional demo with AI-generated photos. Before: uneven latch-side gap. After: a narrower, uniform seam.

Finding 1 · Door alignment at entrance

Before



After



Fictional demonstration. AI-generated example photos. Not an actual inspection.

Delivery note

Prepared for the fictional office facilities team. Please review the paired photos alongside the finding and the numbered plan location.

Next action

On the next visit, check that the door closes and latches correctly. Record any remaining concern as a new finding. This is a sample follow-up instruction, not a completed test.

Edited outside Site Inspector

These delivery notes were added to the exported DOCX outside the app. The photos, numbered plan pin and original finding came from the app export. Fictional example with AI-generated photos.