

# Photo inspection report

## Sample office entrance

Site Inspector / Sample project

DEMO-2026-0927

**Report selection: All**

**Assigned to: All**

**Due on or before: All**

**Findings: 1 / 1**


Client: Fictional office

Auditor: Demo inspector

**Unresolved 0 · In progress 0 · Resolved 1**

## Sample office entrance

EXAMPLE PLAN / NOT TO SCALE



Fictional office entrance. Door finding is marked by the app.

### Finding 1 · Door alignment at entrance

Ground floor / entrance door · Resolved

Assigned to: Sample maintenance team

Due date: 2026-09-27

Fictional demo with AI-generated photos. Before: uneven latch-side gap. After: a narrower, uniform seam.



Before



After

Fictional demonstration. AI-generated example photos. Not an actual inspection.